## State of New Jersey NOTIFICATION OF ASBESTOS ABATEMENT (Pursuant to NJAC 8:60 and 5:16)

Date of Notification (1)				Name of Building Owner/Operator (2)									
9 / 6 / 16			Borough of Lindenwold										
Agencies Notified Type Notification	encies Notified Type Notification			Street Address									
	☑ Initial				2001 Egg Harbor Road								
	☐ Amended				City, State, Zip Code								
E BOIT					Lindenwold, NJ 08021								
DCA Emergency justification		Name of Contact Telephone Number											
☐ Cancellation	1	John	Cannon	- Clyde Lattim	er & Sons 609-352-1849								
		FAC	ILITY INF	ORMATION						i			
Name of Facility Where Abatement is Taking Place (3)						Type of Facility							
Lindenwold Pump Station #1						☐ School (K-12) ☐ Subchapter 8 (Other than K-12)							
Street Address						☐ Subchapter o (Other than 17 12) ☐ Other (i.e., private and commercial buildings,							
100 Lake Boulevard						homes, etc.)							
City (5)				374		Square Feet	# of Floors	Bldg. Age					
Lindenwold						5,000	2		70				
County (6) County Co					(STATE USE ONLY) Current Use (Prior if being demolished)								
Camden					Pump Station								
AND THE PROPERTY OF THE PROPER				10.	Name of Abateme	ent Contractor (9)							
Mgmt. & Enviro. Consulting Services				Shade Environmental, LLC									
Street Address					Street Address								
PO Box 341					623 Cutler Avenue								
City, State, Zip Code					City, State, Zip Code								
Chesterfield, NJ 08515					Maple Shade, NJ 08052								
Project Manager for Monitoring Firm Telephone No.					Telephone No. License No.								
				9-298-4070 856-755-0099			00842						
Start Date (10) Scheduled Comple					Name of OSHA Monitor								
09 / 19 / 16 09 / 3				D / 16 EMSL Analytical, Inc.									
Occupancy Status During Abatement (Check only one)					Street Address								
□ Facility Closed/Vacated During Entire Period of Abate				ement 200 Route 130 North									
☐ Abatement Performed Outside of Normal Facility Hol				. ^^4									
Time of Abatement:AMPM/PM				Cinnaminson, NJ 08077									
Scope of Work (Check all that apply)					☐ Full Cor	ntainment with Ne	gative Pressure						
	☐ Full Containment with Negative Pressure tion ☑ Mini-Enclosure												
□ ≥160 sf or ≥260 lf	Tion ☐ Glovebag Procedure												
		Non-Exempted (*) and Non-Friable Procedure  Abatement Type											
Location of Used S Asbestos-Containing Material (ACM)					Description	of		-			_		
					stos Containing M	aterial (ACM)	Amount (Specify	l Rem	Repair	nca	ncle		
TO BE ABATED	lainten	ance/ Staff?	(i.e		ermal systems insulation, surfacing, VAT, or		Removal	\	Encapsulate	Enclosure			
IN Facility (13)					other miscellan		SF or LF)	-		late	(O)		
(10)	Yes	No	N/A										
Throughout		$\boxtimes$		8" Cem	ent Piping		130 LF	$\boxtimes$					
Timoughout					7,007								
		1=							П	П			
		14	4 <u>0</u>						F	H			
1 1 1					T = 77 · · · · · ·	IN (5	1-1			لا			
Name of Negistered Waste Hadier				Waste D No.	Cubic Yards of Waste								
Freehold Cartage				9	2	Cumberland County Landfill							
City, State					Disposal Date	City, State							
Freehold, NJ					09/30/2016	Newburg, PA							
Completed By (Print or Type)					Signature	Date							
Christina Lynch	Oper	ations	Manag	ger	(XI)	a/re/le							